



Government of Maharashtra, India

Public Works Department

कार्यकारी अभियंता, सार्वजनिक बांधकाम विभाग, औरंगाबाद.

यांचे कार्यालय

पदमपुरा परिसर, औरंगाबाद-४३१००५, दुरध्वनी ०२४०-२३३११७४, फॅक्स ०२४०-२३३४१९२

Email aurangabad.ee@mahapwd.com

जा.क्र./ 849

दिनांक :- 29 / 1 / 2020

Building Safety Certificate

This is to be certified that the physical inspection of the construction of the RCC (parking G+1) Buildings of Chaitanya Valley International School, in Gut No.224, Karmad in Aurangabad Dist. Has been done on 28/01/2020.

Based on intensive visual observation during the visit and subsequent qualitative and quantitative assessment such as ND testing and photograph etc.

Following observations are made

- 1) The various structural elements of the building such as slabs, beams, and columns in good condition as present.
- 2) The indirect compressive strength of concrete by rebound hammer test is in the range of 25.5 Mpa.
- 3) The structure is thoroughly inspected no deflection cracks, spells, crazing seepage etc. No such signs are observed at present.

In view of the above, the structural condition of the building is satisfactory. It is recommended to carryout structural audit in ten year.

Executive Engineer
Public Work Division
Aurangabad.

SECRETARY
Chaitanya Valley International School
Karmad, Tq Dist. Aurangabad.

PRINCIPAL
CHAITANYA VALLEY
International School,
Pimpri Road Karmad,
Tq. Dist. Aurangabad